
# **ASSEMBLY INSTRUCTIONS**

1012A Vertical Breadboard Stamp



Document control number: 1012-8010

Document date: 2022-12-24

Document revision: 1.0.0-draft.3

8 ABSTRACT: This document provides instructions on how to assembly and test a 1012A vertical breadboard

9 stamp. A complete bill of materials is included as an annex.

Suggestions and corrections should be directed to http://www.github.com/dslik/protonema/issues

Serial number: Assembly date: Assembled by:

- 12 USAGE
- Copyright © 2022 David Slik (VE7FIM). All other trademarks or registered trademarks are the property of their respective owners.
- 15 This source describes Open Hardware and is licensed under the CERN-OHL-S v2.
- You may redistribute and modify this source and make products using it under the terms of the CERN-OHL-S v2
- 17 (https://ohwr.org/cern ohl s v2.txt).
- 18 This source is distributed WITHOUT ANY EXPRESS OR IMPLIED WARRANTY, INCLUDING OF MER-
- 19 CHANTABILITY, SATISFACTORY QUALITY AND FITNESS FOR A PARTICULAR PURPOSE. Please see the
- <sup>20</sup> CERN-OHL-S v2 for applicable conditions.
- Source location: https://github.com/dslik/protonema/tree/main/stamps/1012A
- 22 As per CERN-OHL-S v2 section 4, the following notice shall be displayed on product packaging and in the product
- 23 documentation:
- 24 "Based on the Protonema Electronics Prototyping and Learning System by David Slik
- 25 https://www.github.com/dslik/protonema/"
- <sup>26</sup> All code fragments, scripts, and sample code in this document are made available under the following license:
- 27 BSD 3-Clause Software License
- <sup>28</sup> Copyright (c) 2022, David Slik (VE7FIM).
- 29 Redistribution and use in source and binary forms, with or without modification, are permitted provided that the
- <sub>30</sub> following conditions are met:
- \* Redistributions of source code must retain the above copyright notice, this list of conditions and the following
- disclaimer.
- \* Redistributions in binary form must reproduce the above copyright notice, this list of conditions and the following
- disclaimer in the documentation and/or other materials provided with the distribution.
- \* Neither the name of David Slik (VE7FIM) nor the names of its contributors may be used to endorse or promote
- products derived from this software without specific prior written permission.
- 37 THIS SOFTWARE IS PROVIDED BY THE COPYRIGHT HOLDERS AND CONTRIBUTORS "AS IS" AND ANY
- 38 EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF
- MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL
- THE COPYRIGHT OWNER OR CONTRIBUTORS BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPE-
- <sup>41</sup> CIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT
- 42 OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION)
- 43 HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR
- TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFT-
- WARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.
- 46 DISCLAIMER
- 47 The information contained in this publication is subject to change without notice. The author makes no warranty
- of any kind with regard to this document, including, but not limited to, the implied warranties of merchantability
- and fitness for a particular purpose. The author shall not be liable for errors contained herein or for incidental or
- 50 consequential damages in connection with the furnishing, performance, or use of this document.

## 51 Revision history

Table 1: Document Revisions

Version	Date	Change	Approver
1.0.0-draft.1	2022-10-28	Initial draft (missing packaging photos)	D. Slik
1.0.0-draft.2	2022-11-22	Added packaging photos (missing sticker photos)	D. Slik
1.0.0-draft.3	2022-12-24	Added remainder of packaging photos	D. Slik

© VE7FIM 2022 ii

# **Table of contents**

53	I 1012A assembly instructions	1
54	Section 1: Overview	2
55 56 57	Section 2: Prerequisites 2.1 Required safety training	<b>3</b> 3
58 59 60 61 62 63 64 65	Section 3: Preparation  3.1 Workspace 3.2 Project consumables 3.3 Project tools 3.4 Parts preparation 3.4.1 PCBs and PCBAs 3.4.2 Loose components 3.4.3 Packaging materials	5 6 7 10 10 11
66 67	Section 4: Assembly 4.1 1012A assembly	<b>16</b>
68 69 70 71 72	Section 5: Test           5.1 Visual inspection           5.2 QC final check           5.3 QC PASS           5.4 QC FAIL	21 22
73 74	Section 6: Packaging 6.1 1012A packing	<b>24</b> 24
75 76 77 78	Section 7: Clean-up         7.1 Consumables          7.2 Tools          7.3 Workspace	27
79 80	Section 8: Record keeping 8.1 1012A record keeping	<b>30</b>
81 82	Section 9: Process improvement 9.1 Feedback	<b>32</b>
83	II 1012A Annexes	33
84 85	Section 10: Printed Circuit Boards 10.1 1012-0101 PCB	<b>34</b> 34
86 87 88	Section 11: Bill of materials 11.1 1012A Vertical Breadboard Stamp	<b>37</b> 37 37
89 90 91 92 93 94 95 96	Section 12: Reduction of Hazardous Materials         12.1 MG Chemicals 4900          12.2 JLC lead-free PCB          12.3 Global Specialties GS-630          12.4 Global Specialties GS-090          12.5 Molex 0010897041          12.6 Connfly DS1023-2*2SF11          12.7 M3 16mm Nylon Screw          12.8 M3 11mm Nylon Standoff	39 40 41 42 43 44 45 46 47

© VE7FIM 2022 iii

1012-8010 - 1012A assembly instructions v1.0.0-draft.3	
--	--

Public / Controlled

98	12.9 M3 5mm Nylon Screw	48
00	12 10 M3 Nylon Bolt	49

© VE7FIM 2022 iv

# **List of Figures**

101	Fig. 1:	Assembly Desk
102	Fig. 2:	1 pair ESD gloves
103	Fig. 3:	1 spool MG Chemicals 4900 Lead Free No-Clean Wire Solder Sn96.2Ag2.8Cu0.4
104		(96.2/2.8/0.4) 20 AWG
105	Fig. 4:	Tools Container
106	Fig. 5:	Hozan F-23 components tray
107	Fig. 6:	1mm flat-head screwdriver
108	Fig. 7:	3mm Phillips adjustable torque screwdriver
109	Fig. 8:	ESD tweezers
110	Fig. 9:	Fine-tipped Sharpie marker
111	Fig. 10:	Sissors
112	Fig. 11:	1x 1012-0101 v1.0 - Vertical Breadboard Stamp PCB
113	Fig. 12:	1x GS-630A - 630 Tie-Point Solderless Breadboard
114	Fig. 13:	1x GS-090 - 90 Tie-Point Solderless Breadboard (2 pieces)
115	Fig. 14:	1x 0010897041 - Straight 2x4 2.54mm Black Pin Header
116	Fig. 15:	2x DS1023-2*2SF11 - 2.54mm by 2.54mm Straight 2x2P Female Headers
117	Fig. 16:	8x M3 15mm White Nylon Phillips Socket Flat Head Screws
118	Fig. 17:	12x M3 Black Nylon Nuts
119	Fig. 18:	4x M3 5mm Black Nylon Phillips Socket Button Head Screws
120	Fig. 19:	4x M3 11mm+6 Black Nylon Standoffs
121	Fig. 20:	1x QC Sticker
122	Fig. 21:	1x Long size anti-static bag
123	Fig. 22:	1x Small size anti-static bag
124	Fig. 23:	1x Packing box with foam inserts
125	Fig. 24:	2x 1012A Stickers
126	Fig. 25:	Roll of packing tape
	Fig. 26.	1012 0101 DCD with year magnitud connector coldered on
127	Fig. 26:	1012-0101 PCB with rear-mounted connector soldered on
128	Fig. 27:	1012-0101 PCB with front-mounted connectors soldered on
129	Fig. 28:	Breadboard with screwdriver used to make holes in the adhesive backing
130	Fig. 29:	Breadboard with eight screws
131	Fig. 30:	Breadboard with protective paper removed
132	Fig. 31:	1012-0101 PCB with aligned breadboard
133	Fig. 32:	1012-0101 PCB with attached breadboard
134	Fig. 33:	1012-0101 PCB with nuts attached to breadboard screws
135	Fig. 34:	1012-0101 PCB with short screws attached to corner standoffs
	Eig. 25:	Powered 1012-0101 PCB with illuminated 1012-0201 and 1012-0301 power bridges 2
136	Fig. 35: Fig. 36:	1012A with QC Passed sticker
137	Fig. 37:	1012A with QC Passed sticker
138	Fig. 38:	1012A in QC Fail bin
139	1 ig. 50.	Total in Got all bill
140	Fig. 39:	1012A in anti-static bag
141	Fig. 40:	Anti-static bag with nylon nuts in the small anti-static bag.
142	Fig. 41:	1012A in anti-static bag with sticker
143	Fig. 42:	Example photographs of the sealed bag with the serial number written on the sticker
143	Fig. 43:	1012A in box
145	Fig. 44:	1012A in box, sealed with ESD tape.
146	Fig. 45:	1012A in box with sticker
146	Fig. 46:	1012A in box with sticker with serial number.
171	. ig. +o.	20 122 City 2024 Wild October Wild October Hallingon.
148	Fig. 47:	Clean assembly workstation
	9	
149	Fig. 48:	Example of serial number on document cover
	<b>U</b>	
150	Fig. 49:	1012-0101 PCB Front
151	Fig. 50:	1012-0101 PCB Rear

# List of Tables

153	Table 1:	Document Revisions	ii
154	Table 2:	Safety training	3
155	Table 3:	Skills training	4
156	Table 4:	Prepare workspace	5
157	Table 5:	Assembly consumables	6
158	Table 6:	Assembly tools	7
159	Table 7:		0
160	Table 8:		11
161	Table 9:		4
162	Table 10:	1012A assembly steps	16
163	Table 11:		20
164	Table 12:	1012A QC final check	21
165	Table 13:	1012A QC approval	22
166	Table 14:	1012A QC fail	23
167	Table 15:	1012A packaging	24
168	Table 16:	Consumables cleanup	27
169	Table 17:	Tools cleanup	27
170	Table 18:	Workspace cleanup	29
171	Table 19:	1012A record keeping	30
172	Table 20:	1012-0101 PCB	35
173	Table 21:	1012A parts	37
174	Table 22:	1012A packing parts	37
175	Table 23:		10
176	Table 24:	JLC PCB RoHS Compliance	1
177	Table 25:	Global Specialties GS-630	12
178	Table 26:	Global Specialties GS-090	13
179	Table 27:		14
180	Table 28:	Connfly DS1023-2*2SF11 Compliance	<b>ļ</b> 5
181	Table 29:	M3 15mm Nylon Screw RoHS Compliance	16
182	Table 30:	M3 11mm Nylon Standoff RoHS Compliance	١7
183	Table 31:	M3 5mm Nylon Screw RoHS Compliance	18
184	Table 32:		19

© VE7FIM 2022 vi

185

# Part I

# 1012A assembly instructions

### Section 1

## **Overview**

- This document describes the materials, processes, outcomes and verifications required to successfully assemble and test a 1012A vertical breadboard stamp, a sub-component of the Protonema electronics prototyping and learning system.
- <sup>192</sup> A first-time reader should carefully review section 2 prerequisites, and section 3 preparation before beginning the assembly process.
- This document serves both as instructions and as a record of the assembly of the product. When you finish each step in this document, sign your name (or apply your stamp) in the "Signature/Stamp" box on the right to provide a record of completion.
- When things go wrong, this document provides guidance for common issues that have been encountered in the past. When this document does not provide guidance, please contact your quality management representative, who will help you fill out an exception report. These reports help improve process quality and product quality, and these reports are incorporated into future revisions of this document.
- Always remember: If you are unable to successfully complete these instructions, that means the processes supporting you (including this document) have failed you. Our processes are built for your success, and by improving our processes, we help everyone succeed.

## Section 2

# Prerequisites

### 2.1 Required safety training

- <sup>207</sup> The following safety training units must be completed before assembling this product.
- <sup>208</sup> By signing (or applying your stamp) on the right, you indicate that you have completed the following training:

Table 2: Safety training

Item #	Description	Signature/Stamp
1	0102-0100 - Safety reporting policies and procedures training Key topics: Understanding policies and procedures around how to identify, contain and report a safety-related issue in the workplace, including damaged or malfunctioning equipment, leaks, spills, and other occupational hazards.	Stamp or sign here
2	0102-0101 - Material safety data sheets training Key topics: Understanding how to read material safety data sheets (MSDS) for materials you will be handling during product assembly, how they can affect your health and the health of the environment, how to safely handle and dispose of them, and what to do if there is a spill or accidential exposure.	Stamp or sign here
3	0102-0102 - Solder handling and disposal policies and procedures training Key topics: Understanding policies and procedures related to handling solder and solder paste, stencil cleaning, and solder disposal.	Stamp or sign here
4	0102-0105 - Electro-static discharge controls policies and procedures training  Key topics: Understanding policies and procedures related to protecting equipment and components fromm electro-static discharge, including clothing, protective equipment, material handling and labelling.	Stamp or sign here

## 2.2 Required skills training

- The following skills training units must be completed before assembling this product.
- By signing (or applying your stamp) on the right, you indicate that you have completed the following training:

Table 3: Skills training

Item #	Description	Signature/Stamp
1	0103-0202 - ANSI/ESD S20.20 Electro-static discharge controls	
	Key topics: Understanding of ESD safety, the ESD control program, equipment and personnel grounding, EPAs, packaging and marking.	Stamp or sign here
2	0103-0203 - General components handling	
	Key topics: Understanding of safe component handling, including reeled components, components in JEDEC trays, and loose components. Includes avoiding contamination, moisture control, and component inventory management.	Stamp or sign here
3	0103-0414 - 5040-XTS reflow station	
	Key topics: Safe and effective use of the 5040-XTS reflow station, including use of the pre-heater, the hot air system, and the soldering iron. Covers inspection and verification, cleaning, preferred settings and best practice techniques.	Stamp or sign here
4	0103-0301 - IPC-A-610G - Acceptability of electronic assemblies	
	Key topics: Covers visual acceptability requirements for electronic assemblies, including handling considerations, hardware installation, component placement, soldering, terminal connections, wiring, marking and cleanliness.	Stamp or sign here
5	0103-0302 - IPC-J-STD-001F - Soldered electrical connections	
	Key topics: Covers soldering materials, general soldering and assembly requirements, wire and terminal connections, through-hole mounting, surface mounting of components, cleaning process requirements, PCB requirements, coatings and product assurance.	Stamp or sign here

## Section 3

# Preparation

### 3.1 Workspace

<sup>215</sup> Before starting assembly, check out an assembly desk for a minimum of one hour. A single unit can be assembled in ten minutes, with an additional ten minutes per additional unit.




Fig. 1: Assembly Desk

Table 4: Prepare workspace

Step	Description	Signature/Stamp
3.1.1	Verify that the workspace has a clean assembly mat and anti-static mat, and that the cleaning record has been signed since last use.	
		Stamp or sign
		here
3.1.2	Verify that the HEPA fume extractor turns on, and you can feel air suction from the nozzle.	
		Stamp or sign
		here

continues on next page

Table 4 – continued from previous page

Step	Description	Signature/Stamp
3.1.3	Verify that the 5040-XTS rework station soldering iron tip is not worn down. If it is worn down, obtain a new 900M-T-I tip from the stores department.	
		Stamp or sign here

## 3.2 Project consumables

Obtain each of the below consumable items from the stores department:

Table 5: Assembly consumables

Item #	Description	Signature/Stamp
3.2.1		Stamp or sign here
	Fig. 2: 1 pair ESD gloves  If you prefer to use your own pair of ESD gloves, make sure they are tested before use.	
3.2.2	HAPOO-45AG AST 9. III- AND THE SOLDER AST 9. III	Stamp or sign here
	Fig. 3: 1 spool MG Chemicals 4900 Lead Free No-Clean Wire Solder Sn96.2Ag2.8Cu0.4 (96.2/2.8/0.4) 20 AWG	

### 3.3 Project tools

- Obtain a tools container labelled "1XXX Assembly Tools" from the 1XXX section of the stores supply shelf. At your assembly desk, use Table 6 to verify that all the required tools are present.
- If any required tools are missing, return all tools and the tools container to the stores department, and obtain another tools container.




Fig. 4: Tools Container


Remove each of the following tools from the tools container, and place them on the anti-static mat of the assembly desk:



Table 6: Assembly tools

continues on next page

Table 6 – continued from previous page



continues on next page

Table 6 – continued from previous page




### 3.4 Parts preparation

#### 3.4.1 PCBs and PCBAs

- NOTICE: All PCBs and PCBAs must be handled with gloves to prevent marking with skin oils.
- NOTICE: PCBs are removed from manufacturer packaging only when needed.


Table 7: PCBs and PCBAs



#### 3.4.2 Loose components


All loose components are stored on the shelf labelled "1XXX Components". Take the components tray and obtain the following quanities of the following parts:

Table 8: Loose components




continues on next page

Table 8 – continued from previous page



continues on next page


Table 8 – continued from previous page



#### 3.4.3 Packaging materials

All packaging materials are stored on the shelf labelled "1XXX Components". Take the packaging box and obtain the following quanities of the following materials:

Table 9: Packaging materials



continues on next page

Table 9 – continued from previous page

Item#	Table 9 – continued from previous page  Description	Signature/Stamp
3.4.3.4	No marking required	o.g.rataro, otamp
	CORSTAT	Stamp or sign here
	Fig. 23: 1x Packing box with foam inserts	
3.4.3.5	No marking required	
	PACKAGE CONTENTS: IX 1012A VERTICAL BREADBOARD STAMP PACKAG IX 1012A VERTICAL BREADBOARD STAMP 1012-7001 v1	Stamp or sign here
	Fig. 24: 2x 1012A Stickers	
3.4.3.6	No marking required	
		Stamp or sign here
	Fig. 25: Roll of packing tape	


## Section 4

# 237 Assembly

### **4.1 1012A assembly**

<sup>239</sup> This assembly step takes 5 minutes.

Table 10: 1012A assembly steps



continues on next page

Table 10 – continued from previous page

Ct#	Table 10 – continued from previous page	Cianati /Ct
Step # 4.3	Description Snap the two distribution strips (X2, X3) on to each side of the main	Signature/Stamp
7.0	breadboard (X1). Using the slotted screwdriver, make eight holes in the	
	adhesive backing of the breadboard.	Ctomp
		Stamp or sign
		here
	Fig. 28: Breadboard with screwdriver used to make holes in the adhesive	
4.4	backing.  Push the eight white screw through the adhesive layer from the front of the	
7.7	breadboard. While pushing the screw through, you may need to prevent the	
	adhesive from peeling off by holding it with the screwdriver.	Chamar
		Stamp or sign
		here
4.5	Fig. 29: Breadboard with eight screws.	
4.5	Remove the protective paper from the breadboard's adhesive layer.	
		Stamp or sign
		here
	· · · · · · · · · · · · · · · · · · ·	
	Fig. 30: Breadboard with protective paper removed.	
		ontinues on next page


continues on next page

Table 10 – continued from previous page

Step#	Table 10 – continued from previous page  Description	Signature/Stamp
4.6	Align the eight screws with the 1012-0101 PCB, making sure that the text on the breadboard is aligned with the text on the PCB.	Signataro/Otamp*
	the preauboard is alighed with the text of the PCB.	Stamp or sign here
	Fig. 31: 1012-0101 PCB with aligned breadboard.	
4.7	Attach the breadboard to the 1012-0101 PCB by pushing it evenly against the PCB.	Stamp or sign here
	The state which was and the man and the state of the stat	
4.8	Fig. 32: 1012-0101 PCB with attached breadboard.  Screw eight nuts onto the rear of the eight breadboard screws. Do not screw	
7.0	too tightly (finger-tighten only).	Stamp or sign here
	Fig. 33: 1012-0101 PCB with nuts attached to breadboard screws.	ontinues on next page

continues on next page

Table 10 – continued from previous page



# Section 5

# Test

## 5.1 Visual inspection

This test process takes 2 minutes.


Table 11: 1012A visual inspection

Step#	Description	Signature/Stamp
1	Verify that there are no loose parts.	Stamp or sign here
2	Verify that there are no visible fingerprints.	Stamp or sign here

#### 5.2 QC final check

This test process takes 2 minutes.

Table 12: 1012A QC final check



### 5.3 QC PASS

- Only perform these steps if all QC checks have passed.
- This test process takes 1 minutes.


Table 13: 1012A QC approval

Step#	Description	Signature/Stamp
1	Using the tweezers, affix QC Passed sticker in location shown below, then write down the serial number from the QC sticker below the "Signature/Stamp" in the column to the right.  Fig. 36: 1012A with QC Passed sticker	Stamp or sign here
2	Take two photographs, one of the front of the 1012A, and one of the back of the 1012A.	Stamp or sign here

#### 5.4 QC FAIL

- Only perform these steps if any QC check have failed.
- This test process takes 2 minutes.

Table 14: 1012A QC fail



## Section 6

# **Packaging**

### 6.1 1012A packing

This packaging process takes 3 minutes.

Table 15: 1012A packaging

	Table 15: 1012A packaging	
Step#	Description	Signature/Stamp
6.1.1	Place the 1012A module in the anti-static bag.	Stamp or sign here
	Fig. 39: 1012A in anti-static bag.	
6.1.2	Place four nylon nuts in a small anti-static bag, and add the bottom of the bag to the bag the 1012A module is in.	
		Stamp or sign here
	Fig. 40: Anti-static bag with nylon nuts in the small anti-static bag.	

continues on next page

Table 15 – continued from previous page

C+ !!	Table 15 – continued from previous page	Cinn of 101
Step # 6.1.3	Description Seal the anti-static bag with a 1012A sticker.	Signature/Stamp
0.1.0	IO12A	Stamp or sign here
6.1.4	Fig. 41: 1012A in anti-static bag with sticker.  Using the Sharpie pen, Write down the serial number of the 1012A on the sticker, at the end of the line listing the 1012A.	
	IOI2A  PACKAGE CONTENTS  IX IOITA VERTICAL BREADBOARD STA  PAGE 1012 A SECTION 100 Mar. 100 M	Stamp or sign here
6.1.5	Fig. 42: Example photographs of the sealed bag with the serial number written on the sticker  Place 1012A bag in the box on top of the bottom foam padding.	
616	Fig. 43: 1012A in box.  Take a photograph of the 1012A in the box	Stamp or sign here
6.1.6	Take a photograph of the 1012A in the box.	
		Stamp or sign here
	C	ontinues on next page

Table 15 – continued from previous page

Step#	Table 15 – continued from previous page  Description	Signature/Stamp
6.1.7	Using the ESD tape, secure the lid of the box.	orginator ordanip
	ATTENTION OBSERVE REQUITORS FOR HANGLAND ELECTROSTATIC SENSITIVE DEVICES  CORSTAT	Stamp or sign here
	Fig. 44: 1012A in box, sealed with ESD tape.	
6.1.8	Affix a 1012A sticker to the lid of the box.	
	ATTENTION OBSERVE PRECAUTIONS ELECTROSTATIC SENSITIVE DEVICES  Fig. 45: 1012A in box with sticker.	Stamp or sign here
6.1.9	Using the Sharpie pen, Write down the serial number of the 1012A on the	
	sticker, at the end of the line listing the 1012A.  1012A  **Code Contents** Is 1012A  **Code Contents** Is 1012A in box with sticker with social number.	Stamp or sign here
6.1.10	Fig. 46: 1012A in box with sticker with serial number.  Take a photograph of the sealed 1012A box.	
		Stamp or sign here

## Section 7

# <sup>257</sup> Clean-up

## 7.1 Consumables

This packaging process takes 5 minutes.

Table 16: Consumables cleanup

Step#	Description	Signature/Stamp
1	If the ESD gloves have contacted solder paste, or are soiled, they shall be disposed of in the standard waste bin.	
		Stamp or sign here
2	If there is unused solder wire on the spool, it shall be returned to stores.	
		Stamp or sign here
3	Loose component packaging shall be disposed of in the standard waste bin.	
		Stamp or sign here

#### 7.2 Tools

This cleanup process takes 5 minutes.

Table 17: Tools cleanup

Step#	Description	Signature/Stamp
1	All tools shall be returned to the assembly tools container, and returned to the stores supply shelf.	
	If any tools are damaged or worn, return the container to stores, and let the manager know which tool is damaged or worn.	Stamp or sign here

continues on next page


Table 17 – continued from previous page

Step#	Description	Signature/Stamp
2	Remove this document from the springback binder.	Stamp or sign here
3	Print a new copy of this document, and insert it into the springback binder that this document was originally in.	Stamp or sign here
4	Return the springback binder with the newly printed document to the 1012A section of the store supply shelf.	Stamp or sign here

### 7.3 Workspace

This packaging process takes 5 minutes.

Table 18: Workspace cleanup



# **Record keeping**

## 8.1 1012A record keeping

This packaging process takes 5 minutes.

Table 19: 1012A record keeping

Description	Signature/Stamp
Write the serial number, the date, and your first and last name in large print on the bottom of the front cover of this document.	
	Stamp or sign here
FPO	
Fig. 48: Example of serial number on document cover	
Create a new folder under the 1012A folder, named with the serial number.	Stamp or sign here
Copy all photos taken during the assebly process into the newly created folder in step #2.	Stamp or sign here
Remove this document from the binding clamps, scan the document, and save the scanned PDF into the newly created folder in step #2, with the name "1012A-SNAAAAAA.pdf", where AAAAAA is replaced with the serial number.	Stamp or sign here
	FPO  Fig. 48: Example of serial number on document cover  Create a new folder under the 1012A folder, named with the serial number.  Copy all photos taken during the assebly process into the newly created folder in step #2.  Remove this document from the binding clamps, scan the document, and save the scanned PDF into the newly created folder in step #2, with the name "1012A-SNAAAAAA.pdf", where AAAAAA is replaced with the serial

continues on next page

Table 19 – continued from previous page

Step#	Description	Signature/Stamp
5	Three-hole punch the document, then file it at the end of the current month's assembly records binder.	Stamp or sign here
6	Add an entry to the assembly records binder, " <date> - 1012A - SN# AAAAAA - <your name="">", where <date> is replaced with today's date in ISO-8601 YYYY-MM-DD, where AAAAAA is replaced with the serial number of the 1012A, and where <your name=""> is replaced with your first and last name.</your></date></your></date>	Stamp or sign here

# Process improvement

### 9.1 Feedback

- Please submit an issue to the Protonema Issue Repository (http://www.github.com/dslik/protonema/issues) if you encounter any of the below situations:
  - Error in this document
- Unclear directions

273

276

- Suggested process improvements
  - · Results of QC failure investigations
- Tool change suggestions
- Qualtiy processes and documentation is a team effort. This document would not exist without the participation and contributions of the entire assebly team.
- <sup>280</sup> Thank you for reading this assembly instructions document.
- 281 End of document.


282

# Part II

# 1012A Annexes

- Section 10
- **Printed Circuit Boards**
- 286 10.1 1012-0101 PCB

Table 20: 1012-0101 PCB



continues on next page

1012-0101 PCB COPYRIGHT 2022 VETFIM LCJLCJLCJLC Fig. 50: 1012-0101 PCB Rear

Table 20 – continued from previous page

# **Bill of materials**

## 11.1 1012A Vertical Breadboard Stamp

The parts required to assemble a 1012A are listed in Table 21.

Table 21: 1012A parts

Reference	Qty	Description	Manufacturer	Manufacturer Part	Sup-	Cost
Designation	Qty	Description	Manufacturer	Number	plier	Cost
1012-0101	1	Stamp PCB	JLCPCB	Y339-2154951A	JL-	\$1.26
1012 0101		Stamp 1 02	020.02	1000 210 100 174	CPCB	CAD
X1	1	630 Tie-Point	Global	GS-630	Digikey	\$9.37
		Solderless Breadboard	Specialties			
X2, X3	1	90 Tie-Point	Global	GS-090	Digikey	\$6.14
		Solderless Breadboard	Specialties			
		(2 pieces)				
J3	1	Straight 2x4 2.54mm	Molex	0010897041	Digikey	\$0.68
14 10		Black Pin Headers	CONNELY	D04000 0*00E44	1.000	CAD
J1, J2	3	2.54mm by 2.54mm	CONNFLY	DS1023-2*2SF11	LCSC	\$0.23
		Straight 2x2P Female Header	Elec			CAD
MP1 - MP8	8	Screw - M3 15mm	Order By			\$0.66
IVIP I - IVIPO	0	White Nylon Phillips	Description			CAD
		Socket Flat Head	Description			CAD
MP9 - MP16,	8	Nut - M3 Black Nylon	Order By			\$0.95
MP25 - MP28			Description			CAD
MP17 - MP20	4	Screw - M3 5mm	Order By			\$0.25
		Black Nylon Phillips	Description			CAD
		Socket Button Head				
MP21 - MP24	4	Standoff - M3 11mm+6	Order By			\$0.30
		Black Nylon	Description			CAD
SK1	1	QC Sticker	Order by			\$0.0094
			Description			CAD
Total						\$19.85
						CAD

### **11.2 1012A Packaging**

The parts required to package a 1012A are listed in Table 22.

Table 22: 1012A packing parts

			. 1	1		
Reference Designation	Qty	Description	Manufacturer	Manufacturer Part Number	Sup- plier	Cost
N/A	1	Static Shielding Bag 5" X 10"	SCS	100510	Digikey	\$0.22 CAD
N/A	1	Static Shielding Bag 1.5" X 2.8" Ziplock	Order by Description			\$0.06 CAD
		1.0 X Z.O Zipiook	Decomption			O/ LD

continues on next page

Table 22 – continued from previous page

Reference Designation	Qty	Description	Manufacturer	Manufacturer Part Number	Sup- plier	Cost
N/A	1	CORREC-PAK SHIPPER 9 X 7.5 X 1.5" ID	Conductive Containers, Inc.	3180-3	Digikey	\$11.83 CAD
1012-7001	2	1012A ESD Sticker	Jukebox Print			\$4.00 CAD
Total						\$13.04 CAD

# **Reduction of Hazardous Materials**

295 Compliance declarations, in BOM order.

#### 12.1 MG Chemicals 4900

Table 23: MG Chemicals 4900 RoHS Compliance

#### Declaration for MG Chemicals 4900 -

https://www.mgchemicals.com/downloads/msds/01%20English%20Can-USA%20SDS/sds-4900-4917.pdf



#### ISO 9001:2015 Quality Management System

SAI Global File #004008 Burlington, Ontario, Canada

#### **SAC305 No CLEAN SOLDER WIRE**

4900-4917

California Proposition 65 (Chemicals known to cause cancer or reproductive toxicity, USA)

This product does not contain any of the listed substances.

#### **Europe**

RoHS (Restriction of Hazardous Substances Directive)

This product does not contain any lead, cadmium, mercury, hexavalent chromium, PBB's, PBDE's, DEHP, BBP, DBP, or DIBP and complies with European RoHS regulations.

WEEE (Waste Electrical and Electronic Equipment Directive)

This product is not a piece of electrical or electronics equipment, and is therefore not governed by this regulation.

#### **Section 16: Other Information**

**SDS Prepared by** MG Chemical's Regulatory Department

Date of Review 06 March 2020 Supersedes 09 July 2019

Reason for Changes: Update to the emergency phone number information.

#### Reference

- 1) ACGIH 2017 TLVs and BEIs: Based on the documentation of the threshold limit values for chemical substances and physical agents & biological exposure indices, American Conference of Governmental of Industrial Hygienist Cincinnati, OH (2017).
- 2) All toxicological data were checked against the RTECS (Registry of Toxic Effects of Chemical Substances®)

Section continued on the next page

Page **12** of **13** 

Date of Revision: 06 March 2020 / Ver. 3.01

#### 12.2 JLC lead-free PCB

Table 24: JLC PCB RoHS Compliance



### 12.3 Global Specialties GS-630

Table 25: Global Specialties GS-630

Declaration for Global Specialties GS-630 - N/A



### **Certificate of Compliance**

This is to certify that all products and models manufactured or marketed by Cal Test Electronics, which include the following brand names:

- Cal Test Electronics
- Global Specialties
- Elditest

Are compliant to the Directive 2011/65/EU of 8 June 2011 on the restriction of the use of certain hazardous substances in electrical and electronic equipment, and the Commission Delegation Directive (EU) 2015/863 of 31 March 2015, amending Annex II of Directive 2011/65/EU as regards to the list of restricted substances. This directive is introducing 4 new substances (Phthalates) to the original 6 restricted substances.

#### Substances:

- 1. Lead (Pb) <0.1% = < 1,000 ppm
- 2. Mercury (Hg) <0.1% = <1,000 ppm
- 3. Hexavalent Chromium (CR VI) <0.1% = <1,000 ppm
- 4. Cadmium (Cd) <0.01% = <100 ppm
- 5. Polybrominated Biphenyls (PBB) <0.1% = <1,000 ppm
- 6. Polybrominated Diphenyl Ethers (PBDE) <0.1% = <1,000 ppm
- 7. Bis(2-ethylhexyl) Phthalate (DEHP) <0.1% = <1,000 ppm
- 8. Butyl Benzyl Phthalate (BBP) <0.1% = <1,000 ppm
- Dibutyl Phthalate (DBP) <0.1% = <1,000 ppm</li>
   Diisobutyl Phthalate (DIBP) <0.1% = <1,000 ppm</li>

### Exemptions:

1. Annex III, 6(c) – Copper alloy contains up to 4% lead by weight

Marco A. León

Cal Test Electronics, Inc.

Mar C. Len

13-FEB-2018

Cal Test Electronics 22820 Savi Ranch Parkway Yorba Linda, CA 92887 caltestelectronics.com U.S. Toll Free: 800-572-1028 Phone: 714-221-9330 Fax: 714-921-9849 info@caltestelectronics.com

### 12.4 Global Specialties GS-090

Table 26: Global Specialties GS-090

Declaration for Global Specialties GS-090 - N/A



### **Certificate of Compliance**

This is to certify that all products and models manufactured or marketed by Cal Test Electronics, which include the following brand names:

- Cal Test Electronics
- Global Specialties
- Elditest

Are compliant to the Directive 2011/65/EU of 8 June 2011 on the restriction of the use of certain hazardous substances in electrical and electronic equipment, and the Commission Delegation Directive (EU) 2015/863 of 31 March 2015, amending Annex II of Directive 2011/65/EU as regards to the list of restricted substances. This directive is introducing 4 new substances (Phthalates) to the original 6 restricted substances.

#### Substances:

- 1. Lead (Pb) <0.1% = < 1,000 ppm
- 2. Mercury (Hg) <0.1% = <1,000 ppm
- 3. Hexavalent Chromium (CR VI) <0.1% = <1,000 ppm
- 4. Cadmium (Cd) <0.01% = <100 ppm
- 5. Polybrominated Biphenyls (PBB) <0.1% = <1,000 ppm
- 6. Polybrominated Diphenyl Ethers (PBDE) <0.1% = <1,000 ppm
- 7. Bis(2-ethylhexyl) Phthalate (DEHP) <0.1% = <1,000 ppm
- 8. Butyl Benzyl Phthalate (BBP) <0.1% = <1,000 ppm
- 9. Dibutyl Phthalate (DBP) <0.1% = <1,000 ppm
- 10. Diisobutyl Phthalate (DIBP) <0.1% = <1,000 ppm

#### Exemptions:

1. Annex III, 6(c) - Copper alloy contains up to 4% lead by weight

Marco A. León

Cal Test Electronics, Inc.

Mar C. Len

13-FEB-2018

Cal Test Electronics 22820 Savi Ranch Parkway Yorba Linda, CA 92887 caltestelectronics.com U.S. Toll Free: 800-572-1028 Phone: 714-221-9330 Fax: 714-921-9849 info@caltestelectronics.com

#### 12.5 Molex 0010897041

Table 27: Molex 0010897041 RoHS Compliance

Declaration for Molex 0010897041 - https://www.molex.com/datasheets/rohspdf/0010897041\_rohs.pdf



#### **RoHS Certificate of Compliance**

07/11/2022

Molex is committed to managing the use of chemical substances in accordance with governmental regulations, industry standards, and customer-specific requirements in order to protect the environment. For each part listed, this document provides:

• EU RoHS Compliance Status. EU RoHS status is declared per Directive 2011/65/ EU and its subsequent amendments, including the Directive EU 2015/863 which additionally prohibited four phthalates. Homogeneous materials of parts that are compliant to this legislation have less than 0.1% by weight each of lead, mercury, hexavalent chromium, PBB, PBDE, DBP, BBP, DIBP, DEHP, and 0.01% by weight of cadmium. In situations where an exemption applies, the preceding limits, corresponding to the exempted substance(s), may be higher.

Molex's sole liability for incorrectly certifying a product shall be either replacement of the Molex product or, alternatively and in the sole discretion of Molex, return of the purchase price paid for the relevant Molex product.

For additional information regarding Molex's environmental initiatives and further explanation of this information, please visit <a href="https://www.molex.com">www.molex.com</a>

Haim Elivahu


Director, Global Product Stewardship

Table	Α

Molex Part Number	Part Description	RoHS Compliance Status
0010897041	2.54mm Pitch C-Grid Breakaway Header, Dual Row, Vertical, High Temperature, 4 Circuits, Tin (Sn) Plating, 2.72mm PC Tail Length	Compliant

## 12.6 Connfly DS1023-2\*2SF11

Table 28: Connfly DS1023-2\*2SF11 Compliance



# 12.7 M3 16mm Nylon Screw



Table 29: M3 15mm Nylon Screw RoHS Compliance

## 12.8 M3 11mm Nylon Standoff



Table 30: M3 11mm Nylon Standoff RoHS Compliance

# 12.9 M3 5mm Nylon Screw



Table 31: M3 5mm Nylon Screw RoHS Compliance

## 12.10 M3 Nylon Bolt

Table 32: M3 Nylon Bolt RoHS Compliance

